

	Typ Hits	Search Text	DBs	Time Stamp	C O M M	Error Definition O I R S
1	IS&R 27	(("3414982") or ("3432827") or ("4489478") or ("4500905") or ("4535424") or ("4630096") or ("4672577") or ("4710798") or ("4811082") or ("5001539") or ("5089862") or ("5160987") or ("5191405") or ("5202754") or ("5266912") or ("5283468") or ("5398200") or ("5422435") or ("5426566") or ("5434745") or ("5453952") or ("5455445") or ("5468997") or ("5481090") or ("5481133") or ("5495398") or ("5502289")).PN.	USPAT; US-PGPUB	2003/05/07 13:50		0
2	IS&R 27	(("5523622") or ("5523628") or ("5552963") or ("5561622") or ("5581498") or ("5585675") or ("5612570") or ("5654220") or ("5693552") or ("5696031") or ("5703747") or ("5780925") or ("5781031") or ("5801437") or ("5915167") or ("5969380") or ("5976953") or ("5985693") or ("6057598") or ("6072234") or ("6087722") or ("6133640") or ("6185122") or ("6197641") or ("6208545") or ("6281042") or ("6291858")).PN.	USPAT; US-PGPUB	2003/05/07 14:02		0
3	IS&R 13	(("6307257") or ("6314013") or ("6322903") or ("6337521") or ("6351028") or ("6353265") or ("6355501") or ("20010033030") or ("20010054759") or ("20020024146") or ("20020027275") or ("20020030262") or ("20020030263")).PN.	USPAT; US-PGPUB	2003/05/07 14:24		0
4	BRS 23	Chhor-Khushraw-S.in. Moresco-Larry-L.in.	USPAT; US-PGPUB; EPO; JPO	2003/05/07 14:29		0
5	BRS 235	(smart ic chip memory) near3 (card module) same (resin near5 mold\$3)	USPAT; US-PGPUB	2003/09/21 19:41		0

	Typ	Hits	Search Text	Dbs	Time Stamp	Comments	Error Definition	Errors
6	BRS	157	((smart ic chip memory) near3 (card module) same (resin near5 mold\$3)) same (conduct\$3 connect\$3 terminal\$1 pad\$1 contact\$3)	USPAT; US-PGPUB	2003/09/21 11:09			0
7	BRS	148	(smart ic chip memory) near3 (card module) same (resin near5 mold\$3) same (conduct\$3 connect\$3 terminal\$1 pad\$1 contact\$3)	EPO; JPO; DERWENT; IBM_TDB	2003/09/21 13:48			0
8	IS&R	2	((("5523608") or ("5498388")).PN.	USPAT; US-PGPUB	2003/09/21 10:57			0
9	BRS	4	("4663833"   "4894707"   "5079190"   "5220198").PN.	USPAT	2003/09/21 11:00			0
10	BRS	21	5523608.URPN.	USPAT	2003/09/21 11:05			0
11	BRS	47	((smart ic chip memory) near3 (card module) same (resin epoxy)) same (lead adj frame)	USPAT; US-PGPUB	2003/09/21 12:18			0
12	BRS	74	((smart ic chip memory) near3 (card module) same (resin epoxy)) same (lead adj frame)	EPO; JPO; DERWENT; IBM_TDB	2003/09/21 12:19			0
13	BRS	523	235/441.ccls.	USPAT; US-PGPUB	2003/09/21 14:36			0
14	BRS	1449	235/492.ccls. not 235/441.ccls.	USPAT; US-PGPUB	2003/09/21 15:25			0
15	BRS	130	(902/25.ccls. 902/26.ccls. 902/29.ccls.) not (235/492.ccls. 235/441.ccls.)	USPAT; US-PGPUB	2003/09/21 15:30			0
16	BRS	443	361/737.ccls. not (902/25.ccls. 902/26.ccls. 902/29.ccls. 235/492.ccls. 235/441.ccls.)	USPAT; US-PGPUB	2003/09/21 15:45			0
17	BRS	201	257/679.ccls. not (361/737.ccls. 902/25.ccls. 902/26.ccls. 902/29.ccls. 235/492.ccls. 235/441.ccls.)	USPAT; US-PGPUB	2003/09/21 15:53			0

Type	Hits	Search Text	DBs	Time Stamp	Comments		Error
					Definition	Errors	
18	BRS 411	257/433.ccls. not (257/679.ccls. 361/737.ccls. 902/25.ccls. 902/26.ccls. 902/29.ccls. 235/492.ccls. 235/441.ccls.)	USPAT; US-PGPUB	2003/09/21 20:53			0
19	BRS 0	6274926.pn. and solder\$3	USPAT; US-PGPUB	2003/09/21 19:20			0
20	BRS 1	20030029920.pn. and solder\$3	USPAT; US-PGPUB	2003/09/21 19:25			0
21	BRS 1	20030029920.pn. and wire	USPAT; US-PGPUB	2003/09/21 19:40			0
22	BRS 33	(smart ic chip memory) near3 (card module) same (plate near5 (thermal\$2 heat) near5 conductive)	USPAT; US-PGPUB	2003/09/21 19:46			0
23	BRS 17	(smart ic chip memory) near3 (card module) same (plate near5 (thermal\$2 heat) near5 conductive) near5 (packag\$3 resin cas\$3))	USPAT; US-PGPUB	2003/09/21 20:00			0
24	BRS 21	(smart ic chip memory) near3 (card module) same (memory near5 controller near5 (single same one))	USPAT; US-PGPUB	2003/09/21 20:10			0
25	BRS 21	("4774399"   "4780604"   "4807895"   "4843226"   "4926034"   "5036430"   "5047894"   "5155663"   "5176528"   "5404268"   "5581127"   "5584043"   "5608606"   "5627729"   "5653596"   "5712766"   "5775925"   "5865651"   "6042009"   "6381143"   "6457647").PN.	USPAT	2003/09/21 20:08			0
26	BRS 116	(smart ic chip memory) near3 (card module) near5 ((single same one) near5 (chip ic monolithic))	USPAT; US-PGPUB	2003/09/21 20:12			0
27	BRS 11	(smart ic chip memory) near3 (card module) near5 (single same one) near5 (chip ic monolithic) near5 (control\$3 process\$3 microprocess\$3 microcontrol\$3)	USPAT; US-PGPUB	2003/09/21 20:19			0

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
28	BRS	131	(smart ic chip memory) near3 (card module) near5 (single same one) near5 (chip ic monolithic circuit)	USPAT; US-PGPUB	2003/09/21 20:35			0
29	BRS	59	(smart memory) near3 (card module) near5 (stack\$3 near5 (chip ic))	USPAT; US-PGPUB	2003/09/21 20:51			0
30	BRS	1	nishizawa-hirotaka.in. and 235/\$.ccls.	USPAT; US-PGPUB	2003/09/21 20:52			0